

Dist 4

ARS
KED

reed engineering
GROUP

GEOTECHNICAL CONSULTANTS

June 22, 1992
Project No. 515.9

Texas Water Commission
Municipal Solid Waste Division
P.O. Box 13087
Austin, Texas 78711-3087
ATTN: Mr. Chet Safe

Re: Solid Waste Permit No. 1062-A
Garland Landfill
Dallas County, Texas
Ground Water Sampling Report

Dear Sirs:

The ground water monitoring wells at the subject facility were sampled on June 9 through June 12, 1992. Three well volumes were removed from Monitor Wells MW-1, MW-3A through MW-5, and MW-7 prior to sampling. Monitor Wells MW-2, MW-6 and MW-8A through MW-11 were pumped dry and allowed to recover prior to sampling.


The samples from all wells except MW-8A are being analyzed for Groups 3 and 4 by NDRC Laboratories, Inc., Richardson, Texas. Samples from MW-8A are being analyzed for Groups 1 through 4. Per your letter dated April 13, 1992, MW-10 is also being analyzed for sulphate. NDRC indicates that Texas Water Commission (TWC) should receive the results by the first week in July, 1992.


Texas Water Commission
Municipal Solid Waste Division
Project No. 515.9
June 22, 1992
Page 2

Should you have any questions concerning this information, do not
hesitate to call.

Sincerely,

THE REED ENGINEERING GROUP


F. Whitney Smith, R.G.
Engineering Geologist


Ronald F. Reed, P.E.
Principal Engineer

FWS/RFR/aap

copies submitted: (1) Texas Water Commission/Mr. Chet Safe

(1) City of Garland/Mr. Ken Smith